





May not work because of gate threshold!

Levels at SP are:  
 1.0V or higher for wakeup level  
 0.5..0.8V for flash active level  
 This may not lie inside the MOSFETs gate threshold tolerances!



Project :Flash_Remote_Receiver	File :
Sheet :	Editor : dg
Page 2 of 3	Company :
Date : 2011.10.29 Ver. : 2.31	Comment :